
Purpose Intended: Cutting Qualities

	Clear Window	A Window	B Window	C Window	Select Window
Faces Graded	Poorest Face				
Percentage of Recovery	100%	90%	70%	50%	70%
Size of Cuttings	3' or longer				


Characteristics	Clear Window	A Window	B Window	C Window	Select Window
Rate of Growth	6 rings per inch			4 rings per inch	
Slope of Grain	1 in 8			1 in 6	
Wane	1/2" in thickness and width across one corner only, full length per cutting				
Mineral Streaks	2 per 3' cutting (occasional pieces)			unlimited	
Pockets	not permitted			very small (1/8" x 2" or 1/16" x 3")	
Knots	not permitted			sound and tight pin (1/2") knots	
Slough Knots	one - 1/2" wide on face x 1/2" deep on thickness				
Sapstain	not permitted			medium	
Heartstain	not permitted			unlimited	
Checks (not considered)	one - 4" check per 3' of length				

Window Stock Example #1







Window Stock Example #3



Window Stock Example #5



Window Stock Example #4



Window grades developing from ripping

Window stock is designed to provide a product where cross cutting only is required

May be supplied green or dry, rough or dressed, V.G. / F.G. / M.G. (V.G. preferred)

Poorest Face determines the grade, measure cuttings right up to the knot or other characteristics

Window Stock Grades

Grade		Re	Recovery		
×	Clear	×	100%		
×	A	×	90% or more		
×	В	×	70% or more		
×	C	×	50% or more		
×	Reject	×	less than 50%		

Grade			Recovery		
×	Select	×	70% or more		
×	Reject	×	less than 70%		